
Residuals
Residuals
10
0
−10
−20
60
70
80
90
Fitted values


Standardized Residuals
Standardized residuals
2
1
0
−1
−2
60
70
80
90
Fitted values


Autocorrelation
Residuals i+1
10
0
−10
−20
−20
−10
0
10
Residuals i


Normal Q−Q Plot of
Standardized Residuals
Sample Quantiles
1
0
−1
−2
−2
−1
0
1
2
Theoretical Quantiles


Residuals
Residuals
10
0
−10
−20
60
70
80
90
Fitted values


Standardized Residuals
Standardized residuals
2
1
0
−1
−2
60
70
80
90
Fitted values


Autocorrelation
Residuals i+1
10
0
−10
−20
−20
−10
0
10
Residuals i


Normal Q−Q Plot of
Standardized Residuals
Sample Quantiles
1
0
−1
−2
−2
−1
0
1
2
Theoretical Quantiles


Residuals
Residuals
10
0
−10
−20
60
70
80
90
Fitted values


Standardized Residuals
Standardized residuals
2
1
0
−1
−2
60
70
80
90
Fitted values


Autocorrelation
Residuals i+1
10
0
−10
−20
−20
−10
0
10
Residuals i


Normal Q−Q Plot of
Standardized Residuals
Sample Quantiles
1
0
−1
−2
−2
−1
0
1
2
Theoretical Quantiles


Residuals
Residuals
10
0
−10
−20
60
70
80
90
Fitted values


Standardized Residuals
Standardized residuals
2
1
0
−1
−2
60
70
80
90
Fitted values


Autocorrelation
Residuals i+1
10
0
−10
−20
−20
−10
0
10
Residuals i


Normal Q−Q Plot of
Standardized Residuals
Sample Quantiles
1.0
0.0
−1.0
−2.0
−2
−1
0
1
2
Theoretical Quantiles


Residuals
Residuals
10
0
−10
−20
60
70
80
90
Fitted values


Standardized Residuals
Standardized residuals
2
1
0
−1
−2
60
70
80
90
Fitted values


Autocorrelation
Residuals i+1
10
0
−10
−20
−20
−10
0
10
Residuals i


Normal Q−Q Plot of
Standardized Residuals
Sample Quantiles
1.0
0.0
−1.0
−2.0
−2
−1
0
1
2
Theoretical Quantiles


Residuals
Residuals
10
0
−10
−20
60
70
80
90
Fitted values


Standardized Residuals
Standardized residuals
2
1
0
−1
−2
60
70
80
90
Fitted values


Autocorrelation
Residuals i+1
10
0
−10
−20
−20
−10
0
10
Residuals i


Normal Q−Q Plot of
Standardized Residuals
Sample Quantiles
1.0
0.0
−1.0
−2.0
−2
−1
0
1
2
Theoretical Quantiles


Residuals
Residuals
10
0
−10
−20
60
70
80
90
Fitted values


Standardized Residuals
Standardized residuals
2
1
0
−1
−2
60
70
80
90
Fitted values


Autocorrelation
Residuals i+1
10
0
−10
−20
−20
−10
0
10
Residuals i


Normal Q−Q Plot of
Standardized Residuals
Sample Quantiles
1.0
0.0
−1.0
−2.0
−2
−1
0
1
2
Theoretical Quantiles


Residuals
Residuals
10
0
−10
−20
60
70
80
90
Fitted values


Standardized Residuals
Standardized residuals
2
1
0
−1
−2
60
70
80
90
Fitted values


Autocorrelation
Residuals i+1
10
0
−10
−20
−20
−10
0
10
Residuals i


Normal Q−Q Plot of
Standardized Residuals
Sample Quantiles
1.0
0.0
−1.0
−2.0
−2
−1
0
1
2
Theoretical Quantiles


Residuals
Residuals
10
0
−10
−20
60
70
80
90
Fitted values


Standardized Residuals
Standardized residuals
2
1
0
−1
−2
60
70
80
90
Fitted values


Autocorrelation
Residuals i+1
10
0
−10
−20
−20
−10
0
10
Residuals i


Normal Q−Q Plot of
Standardized Residuals
Sample Quantiles
1
0
−1
−2
−2
−1
0
1
2
Theoretical Quantiles


Residuals
Residuals
10
0
−10
−20
60
70
80
90
Fitted values


Standardized Residuals
Standardized residuals
2
1
0
−1
−2
60
70
80
90
Fitted values


Autocorrelation
Residuals i+1
10
0
−10
−20
−20
−10
0
10
Residuals i


Normal Q−Q Plot of
Standardized Residuals
Sample Quantiles
1
0
−1
−2
−2
−1
0
1
2
Theoretical Quantiles


Residuals
Residuals
10
0
−10
−20
60
70
80
90
Fitted values


Standardized Residuals
Standardized residuals
2
1
0
−1
−2
60
70
80
90
Fitted values


Autocorrelation
Residuals i+1
10
0
−10
−20
−20
−10
0
10
Residuals i


Normal Q−Q Plot of
Standardized Residuals
Sample Quantiles
1
0
−1
−2
−2
−1
0
1
2
Theoretical Quantiles


Residuals
Residuals
10
0
−10
−20
60
70
80
90
Fitted values


Standardized Residuals
Standardized residuals
2
1
0
−1
−2
60
70
80
90
Fitted values


Autocorrelation
Residuals i+1
10
0
−10
−20
−20
−10
0
10
Residuals i


Normal Q−Q Plot of
Standardized Residuals
Sample Quantiles
1
0
−1
−2
−2
−1
0
1
2
Theoretical Quantiles


Residuals
Residuals
10
0
−10
−20
60
70
80
90
Fitted values


Standardized Residuals
Standardized residuals
2
1
0
−1
−2
60
70
80
90
Fitted values


Autocorrelation
Residuals i+1
10
0
−10
−20
−20
−10
0
10
Residuals i


Normal Q−Q Plot of
Standardized Residuals
Sample Quantiles
1
0
−1
−2
−2
−1
0
1
2
Theoretical Quantiles